Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVOLTE Page Number : A1 of A3
Report Issued Date : May 11, 2015
Report Version : Rev. 01

Report No.: FC531001


<Radiated Emission>

Mode 1

LF



HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVOLTE Page Number : A2 of A3
Report Issued Date : May 11, 2015
Report Version : Rev. 01

Report No. : FC531001


Report No.: FC531001

Mode 3

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVOLTE Page Number : A3 of A3
Report Issued Date : May 11, 2015
Report Version : Rev. 01