3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Vivo 4.65 HD

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 10 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

BLU

Model: Vivo 4.65 HD
Part No.: D930i
FCC ID: YHLBLUVIVO465

IME1:012345678910123

Designed by BLU in Miami
Assembled in China


Assembled in China

Brand Name: BLU; Model Name: Vivo 4.65 HD


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 11 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 12 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 13 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 14 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 15 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 16 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 17 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 18 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 19 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 20 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 21 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 22 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 23 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01

Report No.: EP2D1808



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO465 Page Number : 24 of 24
Report Issued Date : Jan. 08, 2013
Report Version : Rev. 01