

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B1 of B2
Report Issued Date : Apr. 19, 2013

Report No.: FR332505B

Report Version : Rev. 01







<Radiated Emission>

Report No.: FR332505B

LF





HF

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: +86-755-3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B2 of B2 Report Issued Date: Apr. 19, 2013

: Rev. 01 Report Version