# Appendix A. Setup Photographs

### <Conducted Emission>

#### Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHX2 Page Number : A1 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.2

Report No.: FC612803

## <Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHX2 Page Number : A2 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.2

Report No. : FC612803


C Test Report No. : FC612803

#### Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHX2 Page Number : A3 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2