3. Internal Photograph of EUT

Brand Name: BLU / Model Name: Studio 5.0 C e

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 11 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 12 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 13 of 29
Report Issued Date : Sep. 05, 2014

Report Version

: Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 14 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 15 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 16 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 17 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 18 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 19 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 20 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01


Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 21 of 29
Report Issued Date : Sep. 05, 2014


Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 22 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 23 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 24 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004




TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 25 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 26 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 27 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 28 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report No.: EP471004



TEL: 86-755-3320-2398 FCC ID: YHLBLUST50CE Page Number : 29 of 29
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01