3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.3S

Report No.: EP330701



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 11 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 12 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 13 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: EP330701




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 14 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: EP330701



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 15 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01




SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S

: 16 of 25 Page Number Report Issued Date : Mar. 29, 2013 Report Version : Rev. 01

Report No.: EP330701



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 17 of 25 Report Issued Date : Mar. 29, 2013 : Rev. 01 Report Version




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S

: 18 of 25 Page Number Report Issued Date : Mar. 29, 2013 Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S

: 19 of 25 Page Number Report Issued Date : Mar. 29, 2013 Report Version : Rev. 01


Report No.: EP330701



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 20 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01


Report No.: EP330701



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 21 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: EP330701





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 22 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 23 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 24 of 25
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : 25 of 25 Report Issued Date : Mar. 29, 2013 Report Version : Rev. 01