


## Appendix B. Setup Photographs

### <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTB70LITE Page Number : B1 of B2
Report Issued Date : Dec. 20, 2012
Report Version : Rev. 01

Report No.: FR2O1301




# Report No.: FR2O1301

### <Radiated Emission>

LF



#### HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTB70LITE Page Number : B2 of B2 Report Issued Date: Dec. 20, 2012 Report Version : Rev. 01