Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZOEY3G Page Number : A1 of A3
Report Issued Date : Sep. 24, 2015
Report Version : Rev. 01

Report No. : FC582709


C Test Report No. : FC582709

Mode 1


<Radiated Emission>

Z Plane

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZOEY3G Page Number : A2 of A3
Report Issued Date : Sep. 24, 2015
Report Version : Rev. 01




Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZOEY3G Page Number : A3 of A3
Report Issued Date : Sep. 24, 2015
Report Version : Rev. 01