


# Appendix D. Setup Photographs

### <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number : D1 of D2
Report Issued Date Dec. 06, 2017
Report Version : Rev. 01

Report No.: FR7O1304B

Report Template No.: BU5-FR15CBT4.0 Version 2.0



## Report No.: FR701304B


#### <Radiated Emission>

#### **Z** Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUPUREVIEW Page Number : D2 of D2
Report Issued Date Dec. 06, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0