

Report No. : FR5N2403C

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOONE Page Number : C1 of C2
Report Issued Date : Mar. 03, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2







<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOONE Page Number : C2 of C2
Report Issued Date : Mar. 03, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR5N2403C