





REPORT No. : SZ19100071W02


Band2 / 5MHz / Low CH / QPSK




Band2 / 5MHz / Low CH / 16QAM




Band2 / 5MHz / Low CH / 64QAM




Band2 / 5MHz / Mid CH / QPSK



Band2 / 5MHz / Mid CH / 16QAM



Band2 / 5MHz / Mid CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 | Fax: 86-755-36698525
Http://www.morlab.cn | E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


Band2 / 5MHz / High CH / QPSK




Band2 / 5MHz / High CH / 16QAM




Band2 / 5MHz / High CH / 64QAM




Band2 / 10MHz / Low CH / QPSK



Band2 / 10MHz / Low CH / 16QAM



Band2 / 10MHz / Low CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555
Fax: 86-755-36698525
Http://www.morlab.cn
E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


Band2 / 10MHz / Mid CH / QPSK




Band2 / 10MHz / Mid CH / 16QAM




Band2 / 10MHz / Mid CH / 64QAM




Band2 / 10MHz / High CH / QPSK



Band2 / 10MHz / High CH / 16QAM




Band2 / 10MHz / High CH / 64QAM






REPORT No. : SZ19100071W02


Band2 / 15MHz / Low CH / QPSK




Band2 / 15MHz / Low CH / 16QAM




Band2 / 15MHz / Low CH / 64QAM




Band2 / 15MHz / Mid CH / QPSK



Band2 / 15MHz / Mid CH / 16QAM



Band2 / 15MHz / Mid CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555
Fax: 86-755-36698525
Http://www.morlab.cn
E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


Band2 / 15MHz / High CH / QPSK




Band2 / 15MHz / High CH / 16QAM




Band2 / 15MHz / High CH / 64QAM




Band2 / 20MHz / Low CH / QPSK



Band2 / 20MHz / Low CH / 16QAM




Band2 / 20MHz / Low CH / 64QAM






REPORT No. : SZ19100071W02


Band2 / 20MHz / Mid CH / QPSK




Band2 / 20MHz / Mid CH / 16QAM




Band2 / 20MHz / Mid CH / 64QAM




Band2 / 20MHz / High CH / QPSK



Band2 / 20MHz / High CH / 16QAM



Band2 / 20MHz / High CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




Band4 / 1.4MHz / Low CH / QPSK




Band4 / 1.4MHz / Low CH / 16QAM




Band4 / 1.4MHz / Low CH / 64QAM




Band4 / 1.4MHz / Mid CH / QPSK



Band4 / 1.4MHz / Mid CH / 16QAM




Band4 / 1.4MHz / Mid CH / 64QAM






REPORT No. : SZ19100071W02


Band4 / 1.4MHz / High CH / QPSK




Band4 / 1.4MHz / High CH / 16QAM




Band4 / 1.4MHz / High CH / 64QAM




Band4 / 3MHz / Low CH / QPSK



Band4 / 3MHz / Low CH / 16QAM



Band4 / 3MHz / Low CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


Band4 / 3MHz / Mid CH / QPSK




Band4 / 3MHz / Mid CH / 16QAM




Band4 / 3MHz / Mid CH / 64QAM




Band4 / 3MHz / High CH / QPSK



Band4 / 3MHz / High CH / 16QAM



Band4 / 3MHz / High CH / 64QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No. : SZ19100071W02


Band4 / 5MHz / Low CH / QPSK




Band4 / 5MHz / Low CH / 16QAM




Band4 / 5MHz / Low CH / 64QAM




Band4 / 5MHz / Mid CH / QPSK



Band4 / 5MHz / Mid CH / 16QAM



Band4 / 5MHz / Mid CH / 64QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555
Fax: 86-755-36698525
Http://www.morlab.cn
E-mail: service@morlab.cn