

Report No. : FC231606

Appendix B. Setup Photographs

<Conducted Emission>



Mode 2



Mode 4


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH Page Number : B1 of B2
Report Issued Date : Apr. 06, 2012
Report Version : Rev. 01


CC Test Report No.: FC231606

<Radiated Emission>

Mode 4



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH Page Number : B2 of B2
Report Issued Date : Apr. 06, 2012
Report Version : Rev. 01