3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 7.0

Report No.: EP470101



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 12 of 31
Report Issued Date : Sep. 10, 2014

Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 13 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101

Brand Name: BLU; Model Name: Studio 7.0



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 14 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 15 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 16 of 31
Report Issued Date : Sep. 10, 2014

: Rev. 01


Report Version

Report No.: EP470101




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 17 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 18 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 19 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 20 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01


Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 21 of 31
Report Issued Date : Sep. 10, 2014

Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 22 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01



Report No.: EP470101




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70

: 23 of 31 Page Number Report Issued Date : Sep. 10, 2014 Report Version : Rev. 01



Report No.: EP470101




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70

: 24 of 31 Page Number Report Issued Date : Sep. 10, 2014 Report Version : Rev. 01



Report No.: EP470101



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70


: 25 of 31 Page Number Report Issued Date : Sep. 10, 2014 Report Version : Rev. 01

Report No.: EP470101




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 26 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 27 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01

Report No.: EP470101




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 28 of 31
Report Issued Date : Sep. 10, 2014

: Rev. 01

Report Version

Report No.: EP470101



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 29 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01



Report No.: EP470101



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70

: 30 of 31 Page Number Report Issued Date : Sep. 10, 2014 Report Version : Rev. 01

Report No.: EP470101

Bluetooth & WLAN Antenna <Tx / Rx> GPS Antenna <Rx>



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO70 Page Number : 31 of 31
Report Issued Date : Sep. 10, 2014
Report Version : Rev. 01