

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 2



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDASHMUS40 Page Number : A1 of A2
Report Issued Date : Sep. 09, 2013
Report Version : Rev. 01

Report No. : FC381616



Report No.: FC381616


<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDASHMUS40

: A2 of A2 Page Number Report Issued Date: Sep. 09, 2013 Report Version : Rev. 01