3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 e

Report No.: EP3D1103



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 11 of 26
Report Issued Date : Jan. 21, 2014

Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 12 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 13 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01

Report No.: EP3D1103


Report No.: EP3D1103

Brand Name: BLU; Model Name: Studio 5.0 e



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 14 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01


Report No.: EP3D1103



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 15 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01




Report No.: EP3D1103



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 16 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01




Report No.: EP3D1103



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 17 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01


Report No.: EP3D1103



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 18 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01




Report No.: EP3D1103



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 19 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01




Report No.: EP3D1103




TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 20 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01

Report No.: EP3D1103




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 21 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1103




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 22 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1103



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 23 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01


Report No.: EP3D1103



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 24 of 26
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01



Report No.: EP3D1103



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 25 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01

Report No.: EP3D1103



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO50E Page Number : 26 of 26 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01