


Report No. : FA441002

Appendix D. Test Setup Photos






Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Report Issued Date: May 07, 2014 FCC ID: YHLBLUVIVOIV Page D1 of D2 Form version. : 140305






Report No.: FA441002

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595 Report Issued Date: May 07, 2014

FCC ID: YHLBLUVIVOIV Form version. : 140305 Page D2 of D2