



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A66 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A67 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5




Page Number : A68 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5

Conducted Band Edge


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A69 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 1.5




Page Number : A70 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A71 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A72 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTXLLTE Page Number : A73 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A74 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A75 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A76 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A77 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A78 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A79 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A80 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A81 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A82 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5




Page Number : A83 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A84 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A85 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5



Page Number : A86 of A151
Report Issued Date : Jul. 11, 2016
Report Version : Rev. 01
Report Template No.: BU5-FGLTE Version 1.5