

## <Conducted Emission>

Appendix D. Setup Photographs





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : D1 of D2
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: FR762701B


Report Template No.: BU5-FR15CBT4.0 Version 2.0




## <Radiated Emission>

X plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : D2 of D2
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: FR762701B

Report Template No.: BU5-FR15CBT4.0 Version 2.0