

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : B1 of B2
Report Issued Date : May 27, 2013
Report Version : Rev. 01

Report No.: FR342204B




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : B2 of B2
Report Issued Date : May 27, 2013
Report Version : Rev. 01

Report No.: FR342204B