Appendix B. Setup Photographs



<Conducted Emission>



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B1 of B2
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01

Report No.: FD1D0806





Report No.: FD1D0806

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B2 of B2
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01