


Appendix A. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHJR Page Number : A1 of A2
Report Issued Date : Sep. 11, 2013
Report Version : Rev. 01


Report No. : FG381302






X Plane for 24E

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHJR Page Number : A2 of A2
Report Issued Date : Sep. 11, 2013
Report Version : Rev. 01

Report No. : FG381302