

Report No. : FA381302

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-029-8860-8767 FCC ID: YHLBLUDASHJR Page Number : D1 of D2
Report Issued Date : Sep. 11, 2013
Report Version : Rev. 01






Front of the DUT with Phantom 1 cm Gap



Report No. : FA381302

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: YHLBLUDASHJR Page Number : D2 of D2 Report Issued Date: Sep. 11, 2013 Report Version : Rev. 01