Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVAFLIP Page Number : A1 of A3
Report Issued Date : Mar. 17, 2016
Report Version : Rev. 01


Report Template No.: BU5-FD15B Version 1.2

Report No. : FC611204


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVAFLIP Page Number : A2 of A3
Report Issued Date : Mar. 17, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.2


Report No. : FC611204

Mode 3

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVAFLIP Page Number : A3 of A3
Report Issued Date : Mar. 17, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.2

Report No.: FC611204