

## Appendix B. Setup Photographs

## <Conducted Emission>




TEL: +86-755- 3320-2398 FCC ID: YHLBLULIFEPLAY Page Number : B1 of B2
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: FR350801B






## <Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: +86-755- 3320-2398 FCC ID: YHLBLULIFEPLAY Page Number : B2 of B2
Report Issued Date : Jun. 13, 2013
Report Version : Rev. 01

Report No.: FR350801B