Appendix A. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number : A1 of A4
Report Issued Date : Jan. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7D2005

CC Test Report No. : FC7D2005

Mode 5





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number : A2 of A4
Report Issued Date : Jan. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

<Radiated Emission>

Mode 1

LF



 ${\sf HF}$



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII

: A3 of A4 Page Number Report Issued Date: Jan. 23, 2018 Report Version : Rev. 01

Report No. : FC7D2005


Report Template No.: BU5-FC15B Version 1.3

Mode 5

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number : A4 of A4
Report Issued Date : Jan. 23, 2018
Report Version : Rev. 01

Report No. : FC7D2005

Report Template No.: BU5-FC15B Version 1.3