3. Internal Photograph of EUT

Brand Name: BLU / Model Name: Deejay

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 16 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 17 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 18 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 19 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 20 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 21 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 22 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 23 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 24 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 25 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 26 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 27 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 28 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 29 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 30 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 31 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 32 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 33 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01