

## Appendix B. Setup Photographs

## <Conducted Measurement>







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B1 of B4
Report Issued Date : May 06, 2011
Report Version : Rev. 01









SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B2 of B4
Report Issued Date : May 06, 2011
Report Version : Rev. 01



<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B3 of B4
Report Issued Date : May 06, 2011
Report Version : Rev. 01





<Radiated Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUMAGIC Page Number : B4 of B4
Report Issued Date : May 06, 2011
Report Version : Rev. 01