


**Report No. : FA311501** 

# Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : D1 of D2
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01



## **Report No. : FA311501**

#### **Antenna Location:**



Antenna	Length	Width
WWAN Antenna (Tx / Rx)	3.0cm	1.4cm
Bluetooth Antenna (Tx / Rx)	1.8cm	1.0cm
EUT	9.2cm	5.2cm

The shortest distance between the Tx antennas		
WWAN Antenna (Tx / Rx) to Bluetooth Antenna (Tx / Rx)	0cm	

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : D2 of D2
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01



## **Report No. : FA311501**


## Appendix E. Test Setup Photos





**Right Cheek** 


Right Tilted





Left Cheek

Left Tilted







Back of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : E1 of E1
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01