# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGDXLLTE Page Number : A1 of A3
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC761302

Report No.: FC761302

Mode 4






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGDXLLTE Page Number : A2 of A3
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

# <Radiated Emission>

## Mode 4

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGDXLLTE Page Number : A3 of A3
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC761302