
Appendix A. Setup Photographs

<Radiated Emission>

X Plane for 22H

LF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOX Page Number : A1 of A3
Report Issued Date : Nov. 24, 2014

Report No.: FG4O2207

Report Version : Rev. 01



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOX Page Number : A2 of A3 Report Issued Date: Nov. 24, 2014


Report No.: FG4O2207

Report Version : Rev. 01




X Plane for 24E

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOX Page Number : A3 of A3 Report Issued Date: Nov. 24, 2014

Report No.: FG4O2207

Report Version : Rev. 01