


Report No.: FA3D2801

Appendix D. SAR Test Setup Photos





Right Cheek

Right Tilted






Left Cheek

Left Tilted








Back, Test Separation 1 cm

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEONEX Page Number : D1 of D2 Report Issued Date: Jan. 23, 2014 Report Version : Rev. 01




Left Side, Test Separation 1 cm



Report No.: FA3D2801

Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Front, Test Separation 1 cm (with / Headset)



Back, Test Separation 1 cm (with / Headset)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULIFEONEX Page Number : D2 of D2
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01