

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHM2 Page Number : C1 of C2
Report Issued Date : Mar. 29, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2


Report No.: FR630104C




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHM2 Page Number : C2 of C2
Report Issued Date : Mar. 29, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2

Report No.: FR630104C