
Appendix A. Setup Photographs

<Conducted Emission>

Mode 3






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : A 1 of A 4
Report Issued Date : Jul, 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC761305



Mode 5





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1

Page Number : A 2 of A 4 Report Issued Date : Jul, 12, 2017 Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC761305

<Radiated Emission>

Mode 3

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : A 3 of A 4
Report Issued Date : Jul, 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC761305

C Test Report No.: FC761305

Mode 5

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : A 4 of A 4
Report Issued Date : Jul, 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3