


Report No.: FC331305


Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA


: B1 of B3 Page Number Report Issued Date: Mar. 26, 2013 Report Version : Rev. 01




<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA Page Number : B2 of B3
Report Issued Date : Mar. 26, 2013
Report Version : Rev. 01

Report No.: FC331305






Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDIVA Page Number : B3 of B3
Report Issued Date : Mar. 26, 2013
Report Version : Rev. 01

Report No.: FC331305