1. External Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 S; Marketing Name: Studio 5.0 S

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 1 of 25
Report Issued Date : Apr. 19, 2013

Report No.: EP332505



Brand Name: BLU; Model Name: Studio 5.0 S; Marketing Name: Studio 5.0 S

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 2 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 3 of 25
Report Issued Date : Apr. 19, 2013

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 4 of 25

Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 5 of 25 Report Issued Date : Apr. 19, 2013

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 6 of 25
Report Issued Date : Apr. 19, 2013

: Rev. 01

Report Version

2. Photograph of Accessory

Brand Name: BLU; Model Name: Studio 5.0 S; Marketing Name: Studio 5.0 S

Report No.: EP332505

List of Accessory:

Specification of Accessory		
IAC: Adapter	Brand Name	BLU
	Model Name	US-AH-1000
IRattory	Brand Name	BLU
	Model Name	C665104200T
Earphone	Signal Line Type	120cm, non-shielded cable
USB Cable	Signal Line Type	100cm, shielded cable without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

 ${\it SPORTON\ INTERNATIONAL\ (KUNSHAN)\ INC.}$

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 7 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 8 of 25 Report Issued Date : Apr. 19, 2013

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 9 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 10 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01