
Report No. :FA941714

Appendix D. SAR Test Setup Photos





Right Cheek








Left Tilted Left Cheek

TEL: +86-755-86379589 / FAX: +86-755-86379595

Issued Date: Jun. 03, 2019 FCC ID: YHLBLUB100DL Page D1 of D3 Form version. : 181113





Front, Test Separation 10 mm




Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm




Bottom Side, Test Separation 10 mm

TEL: +86-755-86379589 / FAX: +86-755-86379595

FCC ID: YHLBLUB100DL

Issued Date : Jun. 03, 2019
Page D2 of D3 Form version. : 181113





Front, Test Separation 15 mm

Back, Test Separation 15 mm

Report No. :FA941714

TEL: +86-755-86379589 / FAX: +86-755-86379595

Issued Date: Jun. 03, 2019 FCC ID: YHLBLUB100DL Page D3 of D3 Form version. : 181113