

Report No.: FA0O2916A

## Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : D1 of D2
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01



### FCC SAR Test Report

#### **Antenna Location:**





**WWAN Ant** 

Report No.: FA0O2916A

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : D2 of D2
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01





#### Report No.: FA0O2916A

# Appendix E. Test Setup Photos




**Right Cheek** 





an





Face of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPEED Page Number : E1 of E1
Report Issued Date : Nov. 15, 2010
Report Version : Rev. 01