
Report No. :FA653106

Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted





Left Cheek **Left Tilted**

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

Issued Date: Jul. 04, 2016 Form version.: 160427 Page D1 of D2 FCC ID: YHLBLUVIVO5R







Report No.: FA653106

Front, Test Separation 10 mm


Back, Test Separation 10 mm




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

FCC ID: YHLBLUVIVO5R

Issued Date : Jul. 04, 2016 Form version. : 160427

Page D2 of D2