

Appendix B. Setup Photographs


<Conducted Emission>

Mode 2



Front View

Mode 4



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOPRO Page Number : B1 of B3
Report Issued Date : Feb. 16, 2012
Report Version : Rev. 01

Report No.: FD1D2304






<Radiated Emission>

Mode 2



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOPRO Page Number : B2 of B3
Report Issued Date : Feb. 16, 2012
Report Version : Rev. 01


Report No.: FD1D2304





Mode 4

LF





HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOPRO Page Number : B3 of B3
Report Issued Date : Feb. 16, 2012
Report Version : Rev. 01

Report No.: FD1D2304