1. External Photograph of EUT

Brand Name: BLU / Model Name: SPEED

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 1 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 2 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 3 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 4 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 5 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 6 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: BLU / Model Name: SPEED

Report No.: EP0O2916

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	BLU
	Model Name	SPEED
Battery	Brand Name	BLU
	Model Name	SPEED
Earphone	Brand Name	BLU
	Model Name	SPEED
USB Cable	Brand Name	BLU
	Model Name	SPEED
LCD Panel	Brand Name	truly
	Model Name	TFT1P3433-W-E
Camera 1	Brand Name	truly
	Model Name	CM4858-B200SF-E
Camera 2	Brand Name	Kerr
	Model Name	0000-7491006H1E1G

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 7 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 8 of 26 Report Issued Date : Nov. 24, 2010

Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 9 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 10 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 11 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 12 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 13 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 14 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 15 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 16 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01

Report No.: EP0O2916



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: YHLBLUSPEED Page Number : 17 of 26
Report Issued Date : Nov. 24, 2010
Report Version : Rev. 01