


Appendix A. Setup Photographs

<Radiated Emission>


For 22H

Z Plane

LF



HF



SPORTON INTERNATIOINAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTAR45 Page Number : A1 of A2
Report Issued Date : Sep. 19, 2014
Report Version : Rev. 01


Report No.: FG481106




For 24E

Z Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTAR45 Page Number : A2 of A2
Report Issued Date : Sep. 19, 2014
Report Version : Rev. 01

Report No. : FG481106