Appendix D. SAR Test Setup Photos





Report No. : FA862706

Right Cheek







Left Cheek Left Tilted

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595 Issued Date : Aug. 28, 2018 FCC ID: YHLBLUS5 Page D1 of D2 Form version. : 170509



Front, Test Separation 10 mm



Report No. : FA862706


Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595

FCC ID: YHLBLUS5

Issued Date Page D2 of D2

: Aug. 28, 2018

Form version.

: 170509