

Report No. : FR311501

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : B1 of B2
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01






Report No. : FR311501

<Radiated Emission>



HF

LF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : B2 of B2
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01