
3. Internal Photograph of EUT

Brand Name: BLU / Model Name: VIVO 8L

Report No.: EP762701




Remark:

WWAN Top Antenna (TX / RX): GSM 850/900/1800/1900, WCDMA Band 1/5/8, LTE Band1/3/12/17/28(A+B) WWAN Bottom Antenna (TX / RX): WCDMA Band 2/4, LTE Band 2/4/7

Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 12 of 37
Report Issued Date : Aug. 21, 2017


Report No.: EP762701



Sporton International (Shenzhen) Inc.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 13 of 37
Report Issued Date : Aug. 21, 2017

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 14 of 37
Report Issued Date : Aug. 21, 2017

Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 15 of 37
Report Issued Date : Aug. 21, 2017






Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 16 of 37 Report Issued Date : Aug. 21, 2017




Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 17 of 37 Report Issued Date : Aug. 21, 2017

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 18 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 19 of 37
Report Issued Date : Aug. 21, 2017

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 20 of 37
Report Issued Date : Aug. 21, 2017

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 21 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 22 of 37
Report Issued Date : Aug. 21, 2017

Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 23 of 37 Report Issued Date : Aug. 21, 2017


Report No.: EP762701



Sporton International (Shenzhen) Inc.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 24 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 25 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: EP762701




Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 26 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01




Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 27 of 37

Report Issued Date : Aug. 21, 2017 Report Version : Rev. 01


Report No.: EP762701



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 28 of 37
Report Issued Date : Aug. 21, 2017


Report No.: EP762701



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 29 of 37
Report Issued Date : Aug. 21, 2017
Report Version : Rev. 01

Report No.: EP762701




Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 30 of 37 Report Issued Date : Aug. 21, 2017



Report No.: EP762701




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 31 of 37

Report Issued Date : Aug. 21, 2017 Report Version : Rev. 01




Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 32 of 37 Report Issued Date : Aug. 21, 2017

: Rev. 01 Report Version


Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 33 of 37 Report Issued Date : Aug. 21, 2017



Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 34 of 37 Report Issued Date : Aug. 21, 2017

: Rev. 01 Report Version




Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 35 of 37


Report Issued Date : Aug. 21, 2017 : Rev. 01 Report Version

Report No.: EP762701



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 36 of 37 Report Issued Date : Aug. 21, 2017

Report No.: EP762701



Remark:

WWAN Top Antenna (TX / RX): GSM 850/900/1800/1900, WCDMA Band 1/5/8, LTE Band1/3/12/17/28(A+B) WWAN Bottom Antenna (TX / RX): WCDMA Band 2/4, LTE Band 2/4/7

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8L Page Number : 37 of 37
Report Issued Date : Aug. 21, 2017