


Report No.: FA392412

Appendix D. SAR Test Setup Photos




Right Cheek

Right Tilted







Left Cheek

Left Tilted







Back, Test Separation 1 cm

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUADVANCE45 Page Number : D1 of D2 Report Issued Date: Oct. 30, 2013

Report Version : Rev. 01








Report No. : FA392412

Left Side, Test Separation 1 cm

Bottom Side, Test Separation 1 cm







Right Side, Test Separation 1 cm

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUADVANCE45 Page Number : D2 of D2
Report Issued Date : Oct. 30, 2013

Report Version : Rev. 01