


Report No. : FA350801

Appendix D. SAR Test Setup Photos



Right Cheek





Left Cheek



Right Tilted

Left Tilted



Front, Test Separation 1 cm



Back, Test Separation 1 cm


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL:+86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEPLAY Page Number : D1 of D2 Report Issued Date: Jun 13, 2013 Report Version : Rev. 01





Left Side, Test Separation 1 cm




Report No. : FA350801

Right Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Bottom Side, Test Separation 1 cm

TEL:+86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEPLAY Page Number : D2 of D2
Report Issued Date : Jun 13, 2013
Report Version : Rev. 01