


Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : D1 of D2
Report Issued Date Sep. 30, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0


Report No.: FR790406B



<Radiated Emission> X Plane LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : D2 of D2
Report Issued Date Sep. 30, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0

Report No.: FR790406B