Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHX Page Number : A1 of A3
Report Issued Date : Sep.10, 2015
Report Version : Rev. 01

Report No. : FC581207


C Test Report No. : FC581207

Mode 2


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHX Page Number : A2 of A3
Report Issued Date : Sep.10, 2015
Report Version : Rev. 01

Report No. : FC581207


Mode 3

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHX Page Number : A3 of A3
Report Issued Date : Sep.10, 2015
Report Version : Rev. 01