


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL3 Page Number : B1 of B2
Report Issued Date : Nov. 17, 2015
Report Version : Rev. 01

Report No.: FR5O1505A




<Radiated Emission>




Report No. : FR5O1505A

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL3 Page Number : B2 of B2 Report Issued Date: Nov. 17, 2015 Report Version : Rev. 01