


Report No.: FA3D1802

## Appendix D. SAR Test Setup Photos



**Right Cheek** 





Left Cheek



**Left Tilted** 



Front, Test Separation 1 cm



Back, Test Separation 1 cm

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTAR40

: D1 of D2 Page Number Report Issued Date: Jan. 09, 2014 Report Version : Rev. 01



Left Side, Test Separation 1 cm



Report No.: FA3D1802

Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Back, Test Separation 1 cm (with / Headset)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTAR40 Page Number : D2 of D2
Report Issued Date : Jan. 09, 2014
Report Version : Rev. 01